


# Potential Flood Risk Advisory

District: **Dindigul**

As of **14/05/2021**, the district received **80 to 85 %** of rainfall normal during October to December, and water bodies in the district are **80 to 90 %** full. For the forecasted IMD rainfall condition **Very Heavy Rain**, the the following locations could experience flood inundation based on the past experience.



## Impact in the areas of High Vulnerability - Medium

| No. | Taluk         | Municipality Corporation<br>Division Firka | Revenue Village Ward                          | Location Name                                 |
|-----|---------------|--------------------------------------------|-----------------------------------------------|-----------------------------------------------|
| 1   | DINDIGUL EAST | THEETHAMPATTI, H/O.<br>RAJAKKAPATTI,       | RAJAKKAPATTI PT., / VILLAGE<br>PANCHAYAT      | RAJAKKAPATTI PT., / VILLAGE<br>PANCHAYAT      |
| 2   | DINDIGUL EAST | NGO COLONY, H/O.<br>BALAKRISHNAPURAM       | BALAKRISHNAPURAM PT., /<br>VILLAGE PANCHAYAT  | BALAKRISHNAPURAM PT., /<br>VILLAGE PANCHAYAT  |
| 3   | ATHOOR        | YENIKKAL, H/O.MANALUR                      | MANALUR PT., / VILLAGE<br>PANCHAYAT           | MANALUR PT., / VILLAGE<br>PANCHAYAT           |
| 4   | PALANI        | TAMARAIKULAM                               | TAMARIKULAM PT.,/ VILLAGE<br>PANCHAYAT        | TAMARIKULAM PT.,/ VILLAGE<br>PANCHAYAT        |
| 5   | PALANI        | A.KALYAMPUTHUR                             | A.KALYAMPUTHUR PT., /<br>VILLAGE PANCHAYAT    | A.KALYAMPUTHUR PT., /<br>VILLAGE PANCHAYAT    |
| 6   | PALANI        | PERIAMMAPATTI                              | PERIAMMAPATTI PT., / VILLAGE<br>PANCHAYAT     | PERIAMMAPATTI PT., / VILLAGE<br>PANCHAYAT     |
| 7   | ODDANCHATRAM  | SINDALAVADANPATTI                          | SINDALAVADANPATTI PT., /<br>VILLAGE PANCHAYAT | SINDALAVADANPATTI PT., /<br>VILLAGE PANCHAYAT |
| 8   | VEDASANDUR    | RAJAGOPALAPURAM,<br>VEDASANDUR VILLAGE     | VEDASANDUR TOWN<br>PANCHAYAT                  | VEDASANDUR TOWN<br>PANCHAYAT                  |
| 9   | VEDASANDUR    | NAGAKONUR,<br>VEDASANDUR                   | VEDASANDUR TOWN<br>PANCHAYAT                  | VEDASANDUR TOWN<br>PANCHAYAT                  |
| 10  | KODAIKANAL    | SAVARIKKADU, H/O.<br>VADAGOUNCHI           | VADAGOUNCHI VILLAGE                           | VADAGOUNCHI VILLAGE                           |
| 11  | KODAIKANAL    | DUMDUM PARAI NEAR,<br>H/O.POOLATHUR        | POOLATHUR VILLAGE<br>PANCHAYAT                | POOLATHUR VILLAGE<br>PANCHAYAT                |

### Impact in the areas of Medium Vulnerability - Low

| No. | Taluk         | Municipality Corporation<br>Division Firka | Revenue Village Ward                 | Location Name                        |
|-----|---------------|--------------------------------------------|--------------------------------------|--------------------------------------|
| 1   | DINDIGUL WEST | ATHUPPATTY,<br>H/O.THADICOMBU              | THADICOMBU TOWN<br>PANCHAYAT         | THADICOMBU TOWN<br>PANCHAYAT         |
| 2   | NILAKOTTAI    | ANAIPATTY,<br>H/O.VILAMPATTI               | SITHARGALNATHAM VILLAGE<br>PANCHAYAT | SITHARGALNATHAM VILLAGE<br>PANCHAYAT |
| 3   | NILAKOTTAI    | S.VADIPATTI<br>H/O.SITHARGALNATHAM         | SITHARGALNATHAM VILLAGE<br>PANCHAYAT | SITHARGALNATHAM VILLAGE<br>PANCHAYAT |

**\*\*** Potential Flood risk based on rainfall forecast from Numerical Weather Prediction Model is indicative due to inherent uncertainty of NWP.